STAFF REVIEW AND RECOMMENDATIONS PUBLIC HEARING JUNE 30, 2021

| ABBREVIATES PLAT: | DAIGON ALLEY | |
|---------------------|------------------------------------|------------------|
| LEGAL DESCRIPTION: | SEC 34, T17N, R02E, SEWARD MERIDIA | AN AK |
| PETITIONERS: | TYRA C. GUARD LIVING TRUST | |
| SURVEYOR/ENGINEER: | KEYSTONE SURVEYING/HOLLER ENG | GINEERING |
| ACRES: 5 <u>+</u> | PARCELS: 2 | |
| REVIEWED BY: | AMY OTTO-BUCHANAN | CASE #: 2021-088 |

REQUEST: The request is to create two lots from Tax Parcel B10 to be known as **DAIGON ALLEY**, containing 5 acres +/-. The plat is located south of S. Bodenburg Loop and east of S. Bodenburg Spur, (Tax ID #117N02E34B010); within the E ½ NW ¼ NE ¼ NW ¼ Section 34, Township 17 North, Range 02 East, Seward Meridian, Alaska.

| EXHIBITS | |
|----------------------------------|--------------------------|
| Vicinity Map and Aerial Photos | EXHIBIT A – 4 pgs |
| Geotechnical Report | EXHIBIT B – 4 pgs |
| AGENCY COMMENTS | |
| Department of Public Works | EXHIBIT C – 1 pg |
| Department of Emergency Services | EXHIBIT D – 1 pg |
| Utilities | EXHIBIT E – 7 pgs |
| ADOT&PF | EXHIBIT F – 2 pgs |
| | |

DISCUSSION: The proposed subdivision is located directly south of W. Bodenburg Loop and east of S. Bodenburg Spur. Proposed Parcel 2 is a flag lot; pole portion is 40' wide, as required by MSB 43.20.300(E). S. Bodenburg Loop is owned and maintained by ADOT&PF. The Connex that is 4' from the east lot line will need to be moved (see *Recommendation #5*).

Soils Report: A geotechnical report was submitted (**Exhibit B**), pursuant to MSB 43.20.281(A). Curt Holler, PE, Holler Engineering, notes the soils evaluation included review of existing Holler Engineering soils reports from directly adjacent projects, review and consolidation of existing soils information from the on-lot septic system, review of provided topography information, review of aerial imagery and other observations on site. Testhole location map, topography map and testhole log attached. The project site forms a rectangle shape south of the bordering on S. Bodenburg Loop between The Thornstead and Nelson Farms Phase 1 subdivisions. The majority of the parent parcel contains relatively level terrain with a very minor slope generally to the west. No slopes exceeding 25% were found; total elevation differential is 6'. Parent parcel contains an existing driveway connected to a residential building with related outbuildings. The remainder exists in native or near native state with the exception of a fenced and maintained yard area.

TAXITTATA

Native vegetation is primarily mature growth of varying trees. An existing testhole, originally dug 06/01/2014 in support of an on-lot septic was review and updated. Near surface soils included a "duff" silty topsoil layer extending to 2.5'. Receiving soils are consistently clean well graded extending to 14'. Groundwater was not encountered. Based on the available soils and water table information, topography, code definitions and observations on site, each of the proposed lots will contain over 10,000 sf of contiguous useable septic area and an additional 10,000 sf of buildable area. No construction of streets is required. General existing drainage patterns have been indicated on the map.

<u>Comments</u>: Department of Public Works Operations & Maintenance (Exhibit C) notes approval for additional access to S. Bodenburg Loop must be obtained from ADOT&PF (see *Recommendation #6*). Department of Emergency Services (Exhibit D) has no issues.

<u>Utilities</u>: (Exhibit E) MEA requests a newly recorded easement be shown on final plat (see *Recommendation #4*). MTA has no comments. GCI has no comments or objections. Enstar has no comments or recommendations.

<u>ADOT&PF</u>: (Exhibit F) notes both lots must share access onto S. Bodenburg Loop (see *Recommendation* #6).

At the time of staff report write-up, there were no responses to the Request for Comments from USACE; ADF&G; Community Council Butte; Fire Service Area #2 Butte; Road Service Area #26 Greater Butte; MSB Community Development, Assessments, Planning, Development Services or Pre-Design Division.


<u>CONCLUSION</u>: The preliminary plat of Daigon Alley is consistent with AS 29.40.070 Platting Regulations and MSB 43.15.025 Abbreviated Plats. There were no objections from any federal or state agencies, or Borough departments. There were no objections to the plat from the public in response to the Notice of Public Hearing. Legal and physical access will exist to the proposed lots, consistent with MSB 43.20.100 Access Required, MSB 43.20.120 Legal Access and MSB 43.20.140 Physical Access. Frontage for the subdivision will exist, pursuant to MSB 43.20.320 Frontage and MSB 43.20.300(E) Flag lots. A soils report was submitted, pursuant to MSB 43.20.281(A)(1).

FINDINGS OF FACT

- 1. The plat of Daigon Alley is consistent with AS 29.40.070 Platting Regulations and MSB 43.15.025 Abbreviated Plats.
- 2. A soils report was submitted, pursuant to MSB 43.20.281(A)(1). All lots have required septic and building area.
- 3. All lots will have legal and physical access consistent with MSB 43.20.100, MSB 43.20.120 and MSB 43.20.140.
- 4. Each lot has the required frontage pursuant to MSB 43.20.320.
- At the time of staff report write-up, there were no responses to the Request for Comments from USACE; ADF&G; Community Council Butte; Fire Service Area #2 Butte; Road Service Area #26 Greater Butte; MSB Community Development, Assessments, Planning, Development Services or Pre-Design Division.
- 6. There were no objections from any federal or state agencies, Borough departments, or utilities.
- 7. There were no objections from the public in response to the Notice of Public Hearing.


<u>RECOMMENDATIONS OF CONDITIONS OF APPROVAL</u> for the abbreviated plat of Daigon Alley, Section 34, Township 17 North, Range 02 East, Seward Meridian, Alaska, contingent on staff recommendations:

- 1. Taxes and special assessments must be paid in full for the year of recording, pursuant to MSB 43.15.053(F) and AS 40.15.020. Pay taxes and special assessments (LIDs), by CERTIFIED FUNDS OR CASH.
- 2. Provide updated Certificate to Plat executed within seven (7) days of recording of plat and submit Beneficiary Affidavit for any holders of a beneficial interest.
- 3. Pay postage and advertising fees.
- 4. Show all easements of record on final plat.
- 5. Move the Connex so it is not in setback to the east lot line.
- 6. Apply for driveway permit(s) from ADOT&PF.
- 7. Submit recording fees, payable to Department of Natural Resources (DNR).
- 8. Submit final plat in full compliance with Title 43.











March 31, 2021

Fred Wagner MSB Platting Officer 350 East Dahlia Avenue Palmer, Alaska 99645 RECEIVED JUN 0 41 2021 PLATTING

EXHIBIT B

Re: LB10 S34 T17N R2E Re-Subdivision; Useable Areas, Roads and Drainage HE #21009

Dear Mr. Wagner:

At the request of the project owner, Tyra Guard, we have performed a soils review and related preliminary design work for the referenced proposed subdivision. The project will create 2 new lots from one existing parent parcel totaling 5 acres. Our soils evaluation included review of existing Holler Engineering soils reports for directly adjacent projects, review & consolidation of existing soils information from the on-lot septic system, review of the provided topography information, review of aerial imagery, and our other observations at the site. See the attached testhole location and topography map for details.

<u>Topography.</u> The project site forms a rectangle shape south of and bordering N Bodenburg Loop between *The Thornstead* and *Nelson Farms PH 1* subdivisions. The majority of the parent parcel contains relatively level terrain with a very minor slope generally to the west. No regions containing steep slopes exceeding 25% were found on the parcel. The total elevation differential indicated from the provided topographical map is approximately 6'.

<u>Soils & Vegetation</u>. The parent parcel contains an existing driveway for access connected to a residential building with related outbuildings. The remainder of the project areas appear to exist in either their native or near native state with the exception of a fenced and maintained yard area. The existing native vegetation on the parent parcel primarily consists of mature growth trees of varying kinds. Most foliage consists of thick stands of apparent second growth birch trees with the occasional spruce tree and lesser shrubs and grasses. An existing testhole originally dug on 6/01/14 in support of an on-lot septic was reviewed and updated, and is shown near the proposed new common lot lines. Near surface soils found in the testhole included a "duff" silty topsoil layer extending down to 2.5'. Receiving soils below were found to be consistently clean well graded extending down to 14'. Receiving soils were consistent with Holler Engineering testholes for the parcels immediately to the east and west and directly bordering this project. Groundwater was not encountered in this testhole or in any proximate testhole dug by Holler

Engineering, and groundwater is not expected to be a limiting factor for either of the proposed new lots. A copy of the testhole log and the relevant location/topography map is attached.

<u>Groundwater</u>. Groundwater was not encountered on this project or in any logged testholes. Groundwater is not expected to be a limiting factor for either of the proposed lots.

<u>Useable Areas.</u> The proposed lots have a few limitations on areas defined by MSB code as *useable septic area* or *useable building area*. Useable septic areas will be limited by setbacks to existing water wells, lotlines, and easements. For useable building area, lotlines, utility easements, and ROW/PUE setbacks will be limiting factors. For each of the proposed lots, adequate unencumbered area exists to readily meet the code requirements. Based on the available soils and water table information, topography, MSB Title 43 Code definitions, and our observations at the site, *each of the proposed lots labeled 1 and 2 will each contain over 10,000 square feet of contiguous useable septic area, and an additional 10,000 square feet of useable building area.*

<u>Roads and Drainage</u>. The proposed new lots will be accessed by an existing shared driveway and will not require the construction of any new roads. In this circumstance a drainage plan is not required, however, general existing drainage patterns have also been indicated on the attached map.


Please do not hesitate to call with any other questions you may have.


ncerely

Curtis Holler, PE c: T. Guard, w/attachments



3/31/2021 21010 Soils.doc p.2 / 2





| From: | Jamie Taylor |
|----------|-------------------------------|
| Sent: | Friday, June 25, 2021 4:21 PM |
| То: | Amy Otto-Buchanan |
| Subject: | RE: RFC Daigon Alley #21-088 |

Obtain approval for additional access to Bodenburg Loop from DOT.

Jamie Taylor, PE Civil Engineer Matanuska-Susitna Borough Department of Public Works Operations & Maintenance t: 907-861-7765 c: 907-355-9810 jamie.taylor@matsugov.us http://www.matsugov.us/

From: Amy Otto-Buchanan < Amy.Otto-Buchanan@matsugov.us>

Sent: Friday, June 4, 2021 9:33 AM

To: allen.kemplen@alaska.gov; Nichols, Melanie A (DOT) <melanie.nichols@alaska.gov; Hurn, John T (DOT) <tucker.hurn@alaska.gov; adam.dubour@alaska.gov; regpagemaster@usace.army.mil; John Aschenbrenner <John.Aschenbrenner@matsugov.us>; timhaledistrict1@gmail.com; snowshark1@hotmail.com; Mike and Elaine Shields <meshie@mtaonline.net>; butteakcc@gmail.com; Fire Code <Fire.Code@matsugov.us>; Jill Irsik <Jill.Irsik@matsugov.us>; Eric Phillips <Eric.Phillips@matsugov.us>; msb.hpc@gmail.com; Brad Sworts <Brad.Sworts@matsugov.us>; Cindy Corey <Cindy.Corey@matsugov.us>; Terry Dolan <Terry.Dolan@matsugov.us>; Jim Jenson <James.Jenson@matsugov.us>; Jamie Taylor <Jamie.Taylor@matsugov.us>; Charlyn Spannagel <<Charlyn.Spannagel@matsugov.us>; MSB Farmers <MSB.Farmers@matsugov.us>; Fred Wagner <Frederic.Wagner@matsugov.us>; Theresa Taranto <Theresa.Taranto@matsugov.us>; Andy Dean <Andy.Dean@matsugov.us>; mearow@matanuska.com; row@mtasolutions.com; andrew.fraiser@enstarnaturalgas.com; James Christopher <James.Christopher@enstarnaturalgas.com>; row@enstarnaturalgas.com>; SP Design Group <ospdesign@gci.com>

The following link contains a Request for Comments for a two lot subdivision. Comments are due by June 25, 2021. Please let me know if you have questions. Thanks, A.

https://matsugovus-my.sharepoint.com/:f:/g/personal/amy_ottobuchanan_matsugov_us/EpoKcrcf9jdCjulf6Mj8xeEBiS6W_pDhX0BMxZu6dAQtIA?e=uHZ83s

Please open in Chrome or copy & paste. Opening in Microsoft Edge creates viewing issues.

Amy Otto-Buchanan Platting Technician amy.otto-buchanan@matsugov.us



From: Sent: To: Subject: Fire Code Wednesday, June 16, 2021 2:00 PM Amy Otto-Buchanan RE: RFC Daigon Alley #21-088

Amy, Fire and Life Safety has no issue with this.



Donald Cuthbert

Fire Marshal Fire & Life Safety Division Central Mat-Su Fire Department (907) 861-8030 FireCode@matsugov.us

From: Amy Otto-Buchanan < Amy.Otto-Buchanan@matsugov.us>

Sent: Friday, June 4, 2021 9:33 AM

To: allen.kemplen@alaska.gov; Nichols, Melanie A (DOT) <melanie.nichols@alaska.gov; Hurn, John T (DOT) <tucker.hurn@alaska.gov; adam.dubour@alaska.gov; regpagemaster@usace.army.mil; John Aschenbrenner <John.Aschenbrenner@matsugov.us>; timhaledistrict1@gmail.com; snowshark1@hotmail.com; Mike and Elaine Shields <meshie@mtaonline.net>; butteakcc@gmail.com; Fire Code <Fire.Code@matsugov.us>; Jill Irsik <Jill.Irsik@matsugov.us>; Eric Phillips <Eric.Phillips@matsugov.us>; msb.hpc@gmail.com; Brad Sworts <Brad.Sworts@matsugov.us>; Cindy Corey <Cindy.Corey@matsugov.us>; Terry Dolan <Terry.Dolan@matsugov.us>; Jim Jenson <James.Jenson@matsugov.us>; Jamie Taylor <Jamie.Taylor@matsugov.us>; Charlyn Spannagel <<Charlyn.Spannagel@matsugov.us>; MSB Farmers <MSB.Farmers@matsugov.us>; Fred Wagner <Frederic.Wagner@matsugov.us>; Theresa Taranto <Theresa.Taranto@matsugov.us>; Andy Dean <Andy.Dean@matsugov.us>; mearow@matanuska.com; row@mtasolutions.com; andrew.fraiser@enstarnaturalgas.com; James Christopher <James.Christopher@enstarnaturalgas.com>; row@enstarnaturalgas.com

The following link contains a Request for Comments for a two lot subdivision. Comments are due by June 25, 2021. Please let me know if you have questions. Thanks, A.

https://matsugovus-my.sharepoint.com/:f:/g/personal/amy_ottobuchanan_matsugov_us/EpoKcrcf9jdCjulf6Mj8xeEBiS6W_pDhX0BMxZu6dAQtIA?e=uHZ83s

Please open in Chrome or copy & paste. Opening in Microsoft Edge creates viewing issues.

Amy Otto-Buchanan Platting Technician <u>amy.otto-buchanan@matsugov.us</u> 861-7872

EXHIBIT D



ENSTAR Natural Gas Company

A DIVISION OF SEMCO ENERGY Engineering Department, Right of Way Section 401 E. International Airport Road P. O. Box 190288 Anchorage, Alaska 99519-0288 (907) 277-5551 FAX (907) 334-7798

June 8, 2021

Matanuska-Susitna Borough, Platting Division 350 East Dahlia Avenue Palmer, AK 99645-6488

To whom it may concern:

ENSTAR Natural Gas Company has reviewed the following preliminary plat and has no comments or recommendations.

Daigon Alley
(MSB Case # 2021-088)

If you have any questions, please feel free to contact me at 334-7944 or by email at james.christopher@enstarnaturalgas.com.

Sincerely,

James Christopher

James Christopher Right of Way & Compliance Technician ENSTAR Natural Gas Company



From: Sent: To: Cc: Subject: Attachments: OSP Design Group <ospdesign@gci.com> Monday, June 7, 2021 11:13 AM Amy Otto-Buchanan OSP Design Group RE: RFC Daigon Alley #21-088 RFC Packet.pdf; Agenda Plat.pdf

[EXTERNAL EMAIL - CAUTION: Do not open unexpected attachments or links.] Amy,

In review GCI has no comments or objections to the plat, attached is the signed plat for your records.

Thanks, MIREYA ARMESTO GCI | Technician II, GIS Mapping m: 907-744-5166 | w: <u>www.gci.com</u>

From: Amy Otto-Buchanan < Amy.Otto-Buchanan@matsugov.us>

Sent: Friday, June 4, 2021 9:33 AM

To: allen.kemplen@alaska.gov; Nichols, Melanie A (DOT) <melanie.nichols@alaska.gov>; Hurn, John T (DOT) <tucker.hurn@alaska.gov>; adam.dubour@alaska.gov; regpagemaster@usace.army.mil; John Aschenbrenner <John.Aschenbrenner@matsugov.us>; timhaledistrict1@gmail.com; snowshark1@hotmail.com; Mike and Elaine Shields <meshie@mtaonline.net>; butteakcc@gmail.com; Fire Code <Fire.Code@matsugov.us>; Jill Irsik <Jill.Irsik@matsugov.us>; Eric Phillips <Eric.Phillips@matsugov.us>; msb.hpc@gmail.com; Brad Sworts <Brad.Sworts@matsugov.us>; Cindy Corey <Cindy.Corey@matsugov.us>; Terry Dolan <Terry.Dolan@matsugov.us>; Jim Jenson <James.Jenson@matsugov.us>; Jamie Taylor <Jamie.Taylor@matsugov.us>; Charlyn Spannagel <Charlyn.Spannagel@matsugov.us>; MSB Farmers <MSB.Farmers@matsugov.us>; Planning <MSB.Planning@matsugov.us>; Alex Strawn <Alex.Strawn@matsugov.us>; Fred Wagner <Frederic.Wagner@matsugov.us>; Theresa Taranto <Theresa.Taranto@matsugov.us>; Andy Dean <Andy.Dean@matsugov.us>; mearow@matanuska.com; row@mtasolutions.com; andrew.fraiser@enstarnaturalgas.com; James Christopher <James.Christopher@enstarnaturalgas.com>; subject: RFC Daigon Alley #21-088


[EXTERNAL EMAIL - CAUTION: Do not open unexpected attachments or links.]

The following link contains a Request for Comments for a two lot subdivision. Comments are due by June 25, 2021. Please let me know if you have questions. Thanks, A.

https://matsugovus-my.sharepoint.com/:f:/g/personal/amy_ottobuchanan_matsugov_us/EpoKcrcf9jdCjulf6Mj8xeEBiS6W_pDhX0BMxZu6dAQtIA?e=uHZ83s

Please open in Chrome or copy & paste. Opening in Microsoft Edge creates viewing issues.

Amy Otto-Buchanan Platting Technician amy.otto-buchanan@matsugov.us



From:Holly Sparrow <hsparrow@mtasolutions.com>Sent:Friday, June 4, 2021 11:39 AMTo:Amy Otto-BuchananSubject:RE: RFC Daigon Alley #21-088

[EXTERNAL EMAIL - CAUTION: Do not open unexpected attachments or links.] Hi Amy,

MTA has reviewed the plat for Daigon Alley. MTA has no comments.

Thank you for the opportunity to comment.

Holly Sparrow, Right of Way Agent

MTA | 1740 S. Chugach Street | Palmer, Alaska 99645 office: 907-761-2599 | <u>www.mtasolutions.com</u>



Life. Technology. Together.

From: Amy Otto-Buchanan < Amy.Otto-Buchanan@matsugov.us>

Sent: Friday, June 4, 2021 9:33 AM

To: allen.kemplen@alaska.gov; Nichols, Melanie A (DOT) <melanie.nichols@alaska.gov; Hurn, John T (DOT) <tucker.hurn@alaska.gov; adam.dubour@alaska.gov; regpagemaster@usace.army.mil; John Aschenbrenner <John.Aschenbrenner@matsugov.us>; timhaledistrict1@gmail.com; snowshark1@hotmail.com; Mike and Elaine Shields <meshie@mtaonline.net>; butteakcc@gmail.com; Fire Code <Fire.Code@matsugov.us>; Jill Irsik <Jill.Irsik@matsugov.us>; Eric Phillips <Eric.Phillips@matsugov.us>; msb.hpc@gmail.com; Brad Sworts <Brad.Sworts@matsugov.us>; Cindy Corey <Cindy.Corey@matsugov.us>; Terry Dolan <Terry.Dolan@matsugov.us>; Jim Jenson <James.Jenson@matsugov.us>; Jamie Taylor <Jamie.Taylor@matsugov.us>; Charlyn Spannagel <<Charlyn.Spannagel@matsugov.us>; MSB Farmers <MSB.Farmers@matsugov.us>; Fred Wagner <Frederic.Wagner@matsugov.us>; Theresa Taranto <Theresa.Taranto@matsugov.us>; Andy Dean <Andy.Dean@matsugov.us>; Theresa Taranto <Theresa.Taranto@matsugov.us>; Andy Dean <Andy.Dean@matsugov.us>; mearow@matanuska.com; Right of Way Dept. <row@mtasolutions.com>; andrew.fraiser@enstarnaturalgas.com; James Christopher <James.Christopher@enstarnaturalgas.com>; row@enstarnaturalgas.com; OSP Design Group <ospdesign@gci.com> Subject: RFC Daigon Alley #21-088

The following link contains a Request for Comments for a two lot subdivision. Comments are due by June 25, 2021. Please let me know if you have questions. Thanks, A.

https://matsugovus-my.sharepoint.com/:f:/g/personal/amy_ottobuchanan_matsugov_us/EpoKcrcf9jdCjulf6Mj8xeEBiS6W_pDhX0BMxZu6dAQtIA?e=uHZ83s

Please open in Chrome or copy & paste. Opening in Microsoft Edge creates viewing issues.

Amy Otto-Buchanan Platting Technician <u>amy.otto-buchanan@matsugov.us</u> 861-7872

From: Sent: To: Subject: Attachments: Tammy L. Simmons <Tammy.Simmons@mea.coop> Thursday, June 10, 2021 1:13 PM Amy Otto-Buchanan RE: RFC Daigon Alley #21-088 20210610_132439.pdf

[EXTERNAL EMAIL - CAUTION: Do not open unexpected attachments or links.] MEA comments to include the attached easement in the plat notes.

Thank you.

Tammy Simmons, SR/WA Right of Way Technician 907-761-9276

From: Amy Otto-Buchanan < Amy.Otto-Buchanan@matsugov.us>

Sent: Friday, June 4, 2021 9:33 AM

To: allen.kemplen@alaska.gov; Nichols, Melanie A (DOT) <melanie.nichols@alaska.gov>; Hurn, John T (DOT) <tucker.hurn@alaska.gov>; adam.dubour@alaska.gov; regpagemaster@usace.army.mil; John Aschenbrenner <John.Aschenbrenner@matsugov.us>; timhaledistrict1@gmail.com; snowshark1@hotmail.com; Mike and Elaine Shields <meshie@mtaonline.net>; butteakcc@gmail.com; Fire Code <Fire.Code@matsugov.us>; Jill Irsik <Jill.Irsik@matsugov.us>; Eric Phillips <Eric.Phillips@matsugov.us>; msb.hpc@gmail.com; Brad Sworts <Brad.Sworts@matsugov.us>; Cindy Corey <Cindy.Corey@matsugov.us>; Terry Dolan <Terry.Dolan@matsugov.us>; Jim Jenson <James.Jenson@matsugov.us>; Jamie Taylor <Jamie.Taylor@matsugov.us>; Charlyn Spannagel <<Charlyn.Spannagel@matsugov.us>; MSB Farmers <MSB.Farmers@matsugov.us>; Fred Wagner <Frederic.Wagner@matsugov.us>; Theresa Taranto <Theresa.Taranto@matsugov.us>; Andy Dean <Andy.Dean@matsugov.us>; Theresa Taranto <Theresa.Taranto@matsugov.us>; Andy Dean <Andy.Dean@matsugov.us>; MEA_ROW <MEAROW@mea.coop>; row@mtasolutions.com; andrew.fraiser@enstarnaturalgas.com; James Christopher <James.Christopher@enstarnaturalgas.com>; row@enstarnaturalgas.com>; Subject: RFC Daigon Alley #21-088

CAUTION: This email originated from outside of the MEA.coop organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

The following link contains a Request for Comments for a two lot subdivision. Comments are due by June 25, 2021. Please let me know if you have questions. Thanks, A.

https://matsugovus-my.sharepoint.com/:f:/g/personal/amy_ottobuchanan_matsugov_us/EpoKcrcf9jdCjulf6Mj8xeEBiS6W_pDhX0BMxZu6dAQtIA?e=uHZ83s

Please open in Chrome or copy & paste. Opening in Microsoft Edge creates viewing issues.

Amy Otto-Buchanan Platting Technician amy.otto-buchanan@matsugov.us



Recording District:

Return to:

MEA

163 E. Industrial Way Palmer AK 99654

THIS COVER SHEET HAS BEEN ADDED TO THIS DOCUMENT TO PROVIDE SPACE FOR THE RECORDING DATA. THIS COVER SHEET APPEARS AS THE FIRST PAGE OF THE DOCUMENT IN THE OFFICIAL PUBLIC RECORD.

DO NOT DETACH

Matanuska Electric Association, Inc.

RIGHT OF WAY EASEMENT

KNOW ALL MEN BY THESE PRESENTS, that we the andersigned (whether electr none). 440 E Tri anch: 0x99507. and valuable consideration, the receipt when of is an every acknewledged, to hereby grant unto: E. a cooperative population (the receipt when of its and the Grantee') whose post office address is cassers of assigns, the right to ender unto the lands of the undersigned, situated in the Recording District. State of Alaska, and more particularly described as follows: politis tiereby acknewledged, do hereby grant unto:

The last one her of the Torthinge

peting la Speting <u>27</u>, <u>11</u> (payastita <u>27</u>, <u>14109</u>, <u>11</u>, <u>1</u>

TA WITNESS WHEREOF, the productined hape set their nands and seas Grantor : U Grantor

This is to service the service of th

A rotation of the second s

QUAD: 1000138 Page 2 of 2

2021-016911-0





Department of Transportation and Public Facilities

Program Development and Statewide Planning Anchorage Field Office

> 4111 Aviation Avenue P.O. Box 196900 Anchorage, AK 99519-6900 Main number: 907-269-0520 Fax number: 907-269-0521 Website: dot.state.ak.us

EXHIBIT F

June 16, 2021

Fred Wagner, Platting Officer Matanuska-Susitna Borough 350 East Dahlia Avenue Palmer, Alaska 99645

Re: Plat Review

Dear Mr. Wagner:

The Alaska Department of Transportation and Public Facilities (DOT&PF) has reviewed the following plats and has no comments:

- Philbin Estates (Philbin)
- Tax Map PA 14, Sec 35, T17N, R02E (Nilsson, Smilodon Acres)

The Alaska Department of Transportation and Public Facilities (DOT&PF) has reviewed the following plats and has the following comments:

- Tax Map PA 05, Sec 29, T18N, R02E (Estelle)
 - No direct access will be granted to the Glenn Highway from Parcel #2. According to the Alaska Preconstruction Manual (section 1190), access cannot be granted to the Glenn Highway when there are alternative routes. The existing driveway must be removed.
 - We recommend Parcel D6 establish an official access agreement across Parcel #2 to maintain their future access to Marsh Road. While there is a natural gas easement that they're using at present, they should establish one that guarantees them that they can continue using a driveway across Parcel #2 for future access.
 - No change of access will be granted to Parcel #1.

Daigon Alley (Tyra R Guard Living Trust)

- Both lots must share access onto Bodenburg Loop.
- Spring Hill (Spring Hill Development & Sorensen)
 - As per our comments on 3/11/2021:
 - All lots must use internal access. No direct access will be granted to Palmer-Fishhook for individual lots.
 - We recommend the petitioner dedicate access for the lots to Olivewood Drive. This could provide secondary access to the lots in the future.

"Keep Alaska Moving through service and infrastructure."

All properties accessing DOT&PF roads must apply to Right-of-Way for a driveway permit, subject to provisions listed in 17 AAC 10.020. Any previously issued driveway permits become invalid once the property undergoes a platting action and must be reissued.

We recommend the petitioner verify all section line easements and DOT&PF road rights-of-way adjacent to their property. For assistance, the petitioner may contact the Engineering group within the Right of Way section in DOT&PF at (907) 269-0700. The petitioner is liable to remove any improvements within the easements and rights-of-way that impede the operation and maintenance of those facilities even if they are not shown on the plat, so it is in the petitioner's best interest to identify the exact locations and widths of any such easements or rights-of-way before they improve the property.

If any section line easements or road rights-of-way exist within the bounds of their plat, we recommend the petitioner dedicate them. If there is an existing right-of-way or easement, the petitioner is unable to develop that portion of the property yet continues to pay property taxes on it; dedicating will remove that cost to the petitioner.

If there are any questions regarding these comments please feel free to contact me at (907) 269-0509 or melanie.nichols@alaska.gov.


Sincerely,


Melanie Nichols Mat-Su Area Planner

cc:

Tucker Hurn, Right of Way Agent, Right of Way Scott Thomas, P.E., Regional Traffic Engineer, Traffic Safety and Utilities Brad Sworts, MSB Transportation Manager James Amundsen, Chief, Highway Design Danika Simpson, Property Management Supervisor, Right of Way Jude Bilafer, MSB Capital Projects Director

| YRA C. GUARD-WEILAND, TRUSTEE | | |
|--|------------------------------------|--------|
| YRA C. GUARD LIVING TRUST DATED JANUARY 6, 2006 418 S. BODENBURG LOOP | | |
| ALMER, ALASKA 99645-8548 | | |
| NOTARY ACKNOWLEDGMENT | | |
| JBSCRIBED AND SWORN TO BEFORE ME THIS AY OF, 20 | | |
| DR | | |
| | | i |
| OTARY FOR THE STATE OF ALASKA | | 1 |
| Y COMMISSION EXPIRES | | V |
| | | \sim |
| | | |
| ENEFICIARY | 33' SECTION LNE EASEMENT | > |
| | S89'51'21"E | |
| | 1320.55' FOUND 5/8' REE | |
| IGNATURE DATE | 33' SECTION LNE EASEMENT | |
| | | |
| IAME/TITLE | TITN R2E | |
| ORTGAGE ELECTRONIC REGISTRATION SYSTEMS, INC. (M0. BOX 2026 | MERS) | |
| LINT, MICHIGAN 48501-2026 | | |
| NOTARY ACKNOWLEDGMENT | 46.32 S | |
| JBSCRIBED AND SWORN TO BEFORE ME THIS AY OF, 20 | FOUND 2 1/2" ALUMINUM CAP MONUMENT | |
| DR | | |
| | SPUR 33' - MI RECENT | |
| OTARY FOR THE STATE OF MICHIGAN | | |
| IY COMMISSION EXPIRES | 30DENBURG | |
| CERTIFY THAT THIS SUBDIVISION PLAN HAS BEEN FOUND O COMPLY WITH THE LAND SUBDIVISION REGULATIONS OF HE MATANUSKA-SUSITNA BOROUGH, AND THAT THE PLAT AS BEEN APPROVED BY THE PLATTING AUTHORITY BY | | |
| AT RESOLUTION NO. | | |
| ATED, 20, AND THAT HIS PLAT HAS BEEN APPROVED FOR RECORDING IN THE | | |
| ALMER RECORDING DISTRICT, THIRD JUDICIAL DISTRICT, TATE OF ALASKA, IN WHICH THE PLAT IS LOCATED. | | |
| TATE OF ALASKA, IN WHICH THE FEAT IS ECCATED. | | |
| | | |
| | | |
| DATE PLANNING & LAND USE DIRECTOR | | |
| | | |
| DATE PLANNING & LAND USE DIRECTOR ATTEST: PLATTING CLERK | | |
| ATTEST: | | |
| ATTEST: | | |
| ATTEST:PLATTING CLERK | | |
| ATTEST: | | |
| ATTEST: | SKHEAD EL | |
| ATTEST: | | |
| ATTEST: | DEED RECORDED AT | |
| ATTEST: | | |
| ATTEST: | DEED RECORDED AT | |
| ATTEST: | DEED RECORDED AT | |
| ATTEST: | DEED RECORDED AT | |





0.4' BELOW ASPHALT CONCRETE IN MONUMENT CASE - UNABLE TO READ MARKINGS

NOTES

1. THERE MAY BE FEDERAL, STATE AND LOCAL RE-QUIREMENTS GOVERNING LAND USE. IT IS THE RESPONSIBILITY OF THE INDIVIDUAL PARCEL OWNER TO OBTAIN A DETERMINATION WHETHER SUCH RE-QUIREMENTS APPLY TO THE DEVELOPMENT OF PARCELS SHOWN HEREON.

SCALE 1" = 1 MILE

- 2. BASIS OF BEARING FROM G.P.S. OBSERVATION TAKEN AT THE S.E. CORNER LOT 1, BLOCK 3, NELSON FARMS PHASE 2, PLAT #2014-136
- 3. 5/8" x 30" REBAR WITH SELF-IDENTIFYING PLASTIC CAP SET AT ALL LOT CORNERS, P.C.'S, P.T.'S AND P.R.C.'S UNLESS NOTED.
- 4. NO INDIVIDUAL WATER SUPPLY SYSTEM OR SEWAGE DISPOSAL SYSTEM SHALL BE PERMITTED ON ANY LOT UNLESS SUCH SYSTEM IS LOCATED, CONSTRUCTED AND EQUIPPED IN ACCORDANCE WITH THE REQUIRE-MENTS, STANDARDS AND RECOMMENDATIONS OF THE STATE OF ALASKA, DEPARTMENT OF ENVIRONMENTAL CONSERVATION, WHICH GOVERN THOSE SYSTEMS.
- 5. EASEMENTS OF RECORD NOT PLOTTED HEREON: a) M.E.A. EASEMENT RECORDED OCTOBER 6, 1961 IN BOOK 39 AT PAGE 182
- b) M.E.A. EASEMENT RECORDED DECEMBER 15, 1976 IN BOOK 129 AT PAGE 591


LEGEND

CHECKED BY

GLo

- ⊕ FOUND 2 1/2" BRASS CAP MONUMENT AS SHOWN AND DESCRIBED
- ➡ FOUND 2 1/2" ALUMINUM CAP MONUMENT
- AS SHOWN AND DESCRIBED
- FOUND 5/8" REBAR
- FOUND 5/8" REBAR WITH PLASTIC CAP MARKED LS 7330
- SET 5/8" REBAR WITH SELF-IDENTIFY RECTAINED (T) TOTAL DIMENSION

Agenda Copy JUN 0 -1 2021 SURVEYOR'S CERTIFICATE



SCALE

1 INCH = 100 FEET

SHEET 1 OF 1